

Annexure D

BUILDING SAFETY CERTIFICATENo. 21Dated: 16.04.2025

It is certified that the existing building **Bachpan English School, Sangrur (Punjab)** (name of the building or premises) at **Barnala road, Sangrur** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	03	02	---	---	---	---

The building is owned/occupied by **Bachpan English School, Sangrur (Punjab)** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Public Works Department, Sangrur (PWD)** (Name of Department/ Govt.) on **03-04-2025** (date of inspection) in the presence of **Anu Sudan** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 16.04.2025 for a period of 31.03.2026 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. In the Certificate dated 16.04.2025

2.

3.

4.

Issued on 16.04.2025 at Sangrur by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: _____

Name: Sub Divisional Engineers,

Designation: Provincial Sub Division,

PWD B&R SANGRUR

Name & Address of Department/ Office: _____